## TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS

RESEARCH - DEVELOPMENT - TESTING

14201 FRANKLIN AVENUE TUSTIN, CALIFORNIA 92680 AREA CODE 714 • 730-6239 AREA CODE 213 • 225-1564 C A B L E : T R U E L A B S

February 21, 1990

CLIENT Douglas Aircraft Company

Internal Mail Code 211-46

3855 Lakewood Boulevard

Long Beach, California 90846

SAMPLE Attention: Kathleen Faretta

RECEIVED January 31, 1990

LABORATORY NO.

DATE

35653

Monthly Storm Drain Inspection - January, 1990

P.O. No.: T & M 23465C

**INVESTIGATION** 

As requested by the CRWQCB for NPDES permit numbers CA0001406 and CA0001414

**RESULTS** 

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on January 31, 1990, at the Douglas Long Beach facility (003) and Torrance facilities. The discharge was tested for flow rate, pH, and temperature. The results are as follows:

Sample I.D.	Date	<u>Time</u>	Flow-gpd	Temp, OF	pH, units
Long Beach (003)	1/31/90	10:05	123,149	54	8.0
Torrance	1/31/90	11:45	380	57	7.4

Respectfully submitted, TRUESDAIL LABORATORIES, INC.

Luis Perez, Supervisor Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.